



101056090

Attorney Docket No. 1419.1060
Col/4

UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Yoshinobu KANEKO, et al.

ATTENTION

U.S. Patent No.: 7,094,125

CERTIFICATE OF CORRECTION

Issued: August 22, 2006

BRANCH

For: STEERING DEVICE FOR TOY AND RUNNING TOY

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

*Certificate
OCT 13 2006
of Correction*

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the errors shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the undersigned; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP

By:


William F. Herbert
Registration No. 31,024

Date: 10/10/06

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

10/11/2006 SDENB0B1 00000117 7094125

01 FC:1011

100.00 0P

OCT 16 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 7,094,125

DATED : August 22, 2006

INVENTORS : Yoshinobu KANEKO, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

In column 10, line 36, change "sight" to --right--.
line 48, after "wherein the trim" insert --comprises--.
In column 12, line 49, change "connection" to --connecting--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY
1201 New York Avenue, N.W.
7th Floor
Washington, DC 20005

PATENT NO. 7,094,125

No. of add'l copies
@ 304 per page

⇒

OCT 16 2006